

Appendix A

Actions on MDPH Recommendations Burlington High School Burlington, MA

The following is a status report of action(s) taken on MDPH recommendations (**in bold**) based on reports from building management, office staff, documents, photographs and MDPH, CEH staff observations.

1. Examine the hallway fiberglass insulation for water damage and mold growth.
Remove moldy insulation. Disinfect space above suspended ceiling.
Action Taken: Water damage was remediated in a significant number of areas.
The ceiling system in the hallway remains.
2. Repair roof as soon as possible. Identify and repair all roof leaks to prevent further water damage to walls or ceiling tiles, which could serve as a potential growth media for mold. In addition, appropriate disinfection of the area above the ceiling tiles should also be considered if mold growth is identified in these areas.
Actions Taken: The roof flashing was reported by Mr Robinson to be repaired.
A number of areas of the roof in need of repair remain.
3. Replace all stained fiber ceiling tiles and fiberglass insulation with visible mold growth. Identify areas of water leaks and disinfect appropriately.
Action Taken: Mold colonized ceiling tiles were removed. A number of water damaged ceiling tiles remain in classrooms
4. Replace all water damaged carpets.
Action Taken: Carpeting was replaced.
5. Prevent water penetration into the stage area.

Appendix A

Action Taken: Stage water damage repaired. Water leak repaired.

6. Repair the HVAC system.

Action Taken: Fresh air supplies extended into classrooms where feasible.